

73 Fifth Street SW
Lots 18 and 19, Block 15,
2nd Railway Addition
City of Huron
Beadle County
South Dakota

HABS No. SD-18

HABS
SD
3-HURO,
2-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Rocky Mountain Regional Office
Department of the Interior
P.O. Box 25287
Denver, Colorado 80225

United States Department of the Interior
NATIONAL PARK SERVICE
ROCKY MOUNTAIN REGION

HISTORIC AMERICAN BUILDINGS SURVEY

HABS SD,3-HURON,2-
ARCHITECTURAL DATA FORM

STATE	COUNTY	TOWN OR VICINITY
South Dakota	Beadle	Huron
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)		HABS NO.
73 Fifth Street SW (residential structure)		SD-18
SECONDARY OR COMMON NAMES OF STRUCTURE		
Not Applicable		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)		
73 Fifth Street SW, Huron, South Dakota Lots 18 and 19, Block 15, 2nd Railway Addition		
DATE OF CONSTRUCTION (INCLUDE SOURCE)	ARCHITECT(S) (INCLUDE SOURCE)	
1904 (City Assessor's Office)	Not Known	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)		
This house was constructed as a single family residence and was constructed at a time when 50 percent of the other houses in the Campbell Park Historical District were constructed. Its style reflects a simplistic and moderate architectural form. The structure is located on the periphery of the historical district and has been identified as a contributing structure within the district.		
STYLE (IF APPROPRIATE)		
--		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)		
This is a wood frame house with wood siding and an asphalt shingle roof. The basement is masonry block construction.		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)		
The house is a two story structure with overall dimensions of 27 feet by 58 feet. This includes a 10 foot by 27 foot porch on the front of the house.		
EXTERIOR FEATURES OF NOTE		
The most prominent exterior features to note include: the 10 foot by 27 foot porch on the front of the house and the attic window on the front of the house.		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)		
The house was originally constructed for single family use. Since then the second floor has been converted into an apartment. Overall condition of the interior is fair.		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES		
The building records for the City are incomplete, however it appears that one addition was constructed onto the rear of the original structure. The dimensions of this addition are 14 feet by 27 feet. Its construction date is unknown.		
PRESENT CONDITION AND USE		
Overall condition of the structure is fair. The shingles are in very deteriorated condition, there are cracks in the foundation walls and interior walls. The exterior trim on the house needs painting. The first floor of the structure is currently occupied, the second floor is vacant. The structure is to be moved to a different location in the City by fall of 1983.		
OTHER INFORMATION AS APPROPRIATE		
--		
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)		
Campbell Park Historic District National Register Nominating Form Huron City Assessor's Office Huron Inspection Department		
COMPILER, AFFILIATION		DATE
Patrick J. Ivory, Huron City Planner Affiliated with the City of Huron		July 25, 1983